

SPCPro_V3.7.3		2.2.2017	Updates since: SPCPro_V3.6.6	Feature type (related languages)
<div>CONTENT</div> <div>FlexC events.....2</div> <div>FlexC fixed encryption key2</div> <div>SPC 3.6.6 file support2</div> <div>Support for SPC 3.72</div> <div>ATS Limit 40002</div> <div>Bug fixes 2</div> <div>Language bundles2</div>				

SPCPro_V3.7.3		20.7.2016
FlexC events When using FlexC event exceptions in FlexC event profiles an error has been detected whereby the exception may be applied incorrectly. This would result in the exception applying to a different event. . This has now been addressed	Fix	All

SPCPro_V3.7.2		20.7.2016
FlexC fixed encryption key When using FlexC with a fixed encryption key upload or setting the key in SPC Pro was not successfully stored or set. This has now been addressed	Fix	All

SPCPro_V3.7.1		20.7.2016
SPC 3.6.6 file support An issue has been address where the configuration file may become corrupted when using a SPC 3.6.6 configuration file in SPC Pro 3.7.0	Fix	All
SPCPro_V3.7.0		
Support for SPC 3.7 <ul style="list-style-type: none"> Wireless lost event Auto restore delay Force arm mode Tech zone delay Camera Settings Door attributes 	New	All
ATS Limit 4000 Number of ATSs limited to 3	Change	All
Bug fixes <ul style="list-style-type: none"> Viewing calendar in door section would cause the application to freeze this has now been addressed. FlexC - default event profile additional fields added 	Fix	All
Language bundles Language bundles options have been change to include additional bundles. Options are as follows SPC_SwDkNoFi_36.clng SPC_FrGeSw_36.clng SPC_FrGeSplt_36.clng	New	All

SPC_FrGeltRo_36.cln SPC_FrGeltPo_36.cln SPC_FrGeltDu_36.cln SPC_FrGeFIDu_36.cln SPC_FrGe_36.cln		
END		