

SPC 3.13.1

FIRMWARE RELEASE NOTES

Issue Summary

3.13.1	3
1 Enhancement: Serial interface – Add incremental counter for log print.....	3
2 Bug-fix: Active System Alerts clipped at 16 characters	3
3 Bug-fix: Confirmation timer changes after panel restart	3

3.13.1

NOTES:

Release Date	23 rd April 2021
Additional Notes	

1 Enhancement: Serial interface – Add incremental counter for log print

Feature/ Description	<ul style="list-style-type: none">Enhancement: Serial RS232 interface – Add incremental counter for log print before date and time. Counter starts at 0001 and when it reaches 9999 rolls back to 0001. Serial ports 1 and 2 have independent counters. Note that it is not possible to use serial port 2 and two way wireless simultaneously, meaning if tww is used then the print log is available only in serial port 1.
-------------------------	--

2 Bug-fix: Active System Alerts clipped at 16 characters

Bug Description	Active System Alerts clipped at 16 characters
-----------------	---

3 Bug-fix: Confirmation timer changes after panel restart

Bug Description	Confirmation timer changes after panel restart
-----------------	--